



KONICA MINOLTA

TECHNICAL BULLETIN

Bulletin # 14161
Date: 6/25/2025
Subject: bizhub 7, 8, & 9 Series Firmware G00-Y8 Maintenance Firmware Release

bizhub 227:	0088	bizhub 558e:	0050	bizhub C3351:	0021
bizhub 287:	0089	bizhub 658e:	0050	bizhub C368:	0076
bizhub 308e:	0033	bizhub 808:	0097	bizhub C3851FS:	0025
bizhub 368:	0039	bizhub 958:	0097	bizhub C458:	0099
bizhub 368e:	0033	bizhub C227:	0067	bizhub C558:	0108
bizhub 458:	0051	bizhub C258:	0069	bizhub C658:	0109
bizhub 458e:	0046	bizhub C287:	0066	bizhub C659:	0046
bizhub 558:	0057	bizhub C308:	0075	bizhub C759:	0046

Overview

G00-Y8 is a Maintenance Firmware Release that includes eleven (11) fixes related to machine stability and security.

Action

This firmware can be downloaded from the One-Stop Product Support Site.

Important Note

- **When installing G00-Y8 or later using the following methods, you MUST first install the GXX-A2 Jig Firmware.**
 - WWRSPF
 - FleetRMM
 - Internet ISW
 - Automatic update of the main unit
- It is recommended to leave at least one hour between the start times of the GXX-A2 Jig and G00-Y8 or later.
- The machine can be used with the JIG FW, but it is not recommended for long-term use.
- You DO NOT need to use the GXX-A2 Jig Firmware for USB Installation of G00-Y8 or later.
- If you need to downgrade a machine from firmware version G00-Y8 or later to an earlier version, the firmware must be applied using a USB memory device ONLY.
- Ensure you review KB0032702 prior to installing the G00-Y8 or later for additional details.

Addition of function

- TLS 1.3 Support

Highlights

- Countermeasure for OpenSSL vulnerability (CVE-2022-4304) (CVE-2023-3446/CVE-2023-3817).
- LAN connection prevents screen change and causes rebooting of the device.
- When the network is disconnected during operation of the remote WWRSPF panel, the user can browse the service mode screen on the panel.
- The countermeasure of all the problems solved on GCP-XX or earlier versions are included in this firmware.

Please reference the firmware's associated DLKM for complete details on fixes and enhancements.

For any questions, please contact the Contact Support Center at 1-800-825-5664.